

FIG. 2




FIG. 3




FIG. 5




FIG. 6




FIG. 7




FIG. 8

205090" 225400T

7/58




FIG. 9




FIG. 10

205090" 2262/001




FIG. 11




FIG. 12




FIG. 13




FIG. 14

205090" 2264200T

10/58




FIG. 15




FIG. 16

205090-2262001




FIG. 17




FIG. 18

12/58




FIG. 19




FIG. 20

1007922.050503




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25

205090-2264007




FIG. 26

2007922.06506




FIG. 27




FIG. 28

1007922.060502




FIG. 29




FIG. 30




FIG. 31




FIG. 32

205090-2264001




FIG. 33




FIG. 34




FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40




FIG. 41

205090" 226400T




FIG. 42




FIG. 43

205090" 226200T




FIG. 44




FIG. 45




FIG. 46

1007922-060502




FIG. 47




FIG. 48

205090-226/0001




FIG. 49

205090" 2262200T




FIG. 50




FIG. 51




FIG. 52




FIG. 53

205090" 2264200T




FIG. 54

40/58




FIG. 55




FIG. 56




FIG. 57

205090" 2267/00T




FIG. 58




FIG. 59




FIG. 60

205090 226/001

205090" 2262200T




FIG. 61






FIG. 62



SECRET



SECRET




FIG.66




FIG.67




FIG. 68




FIG. 69

205090-2267001




FIG. 70

205090-2267001

50/58




FIG. 71




FIG. 72

205090 " 226 / 2007




FIG.73




FIG.74




FIG. 75




FIG. 76




FIG. 77




FIG. 78




FIG. 79

55/58




FIG. 80




FIG. 81

205090-226/001




FIG. 82.




FIG. 83




FIG. 84




FIG. 85

20250901 2262001